

Safety Screening Report

Report:	071-75924520-502	Date:	09/01/2014
Client:	The Electrical Safety Council Unit 331 Great Guildford Business Square 30 Great Guildford Street London SE1 0HS		
Product:	Electrical Socket	ESC Sample Number:	7
Summary:	TÜV SÜD Product Service was commissioned by The Electrical Safety Council to evaluate an Electrical Socket (see figure 1). The aim of the assessment is to assess the product against the clients Safety Screening Test Plan.		

Summary

The product failed every section of the report except for the screws, current carrying parts & connections, insulation resistance/leakage current & electric strength. The product is not considered fit for purpose and is a hazard to safety.

Figure 1



Assessed by:

2109

Anna Jeeves Consumer Product Technician

Reviewed by:

Greg Plummer Consumer Product Test Engineer





= Improvements Required



© 2014 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 1 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Testing Information		
Testing Laboratory:	TÜV SÜD Product Service	
Location:	Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire,	
	PO15 5RL. UK.	
Client:	The Electrical Safety Council	
ESC Sample Number:	7	
Product Information		
Product Description:	Single Wall socket with a USB Port	
Rated Input Voltage:	250VAC	
Rated Output:	13A, none stated for the USB socket.	
Protection Class:	Class I	

	Finding	gs	
	Markings/Warnings		
	(BS 1363-2, Cl	lause 7)	
Marking of Product	-Inadequate -Poor -	Adequate 🔄 - Good 🗌 ·	-Very Good 🗌 -N/A
Comments	The product as a unit was un trademark, WEEE log and CE		
	The socket assembly was ma which could not be verified o considered to be UK approve	online. BS 1363 was not	present; therefore not
	The switch was also marked stated was 10A for a 13A soc trademark was missing. The made available / visible to th	ket. A part reference / USB output ratings wer	manufacturer
	There were no instructions s assessment. Information cov should be made available to that the product was suitable cameras and MP3s.	ering general safety, ins the installer / end user.	stallation and operation The packaging stated
Markings/Photo	S-Yes -No	CE Marking	☐-Yes ⊠-No
	Construction (BS 1363-2, Clause 13)		
Product Build Quality	Pass 🛛-Fail		
Comments	The external construction was burrs were found. The mould standard in comparison to sin was slotted into the mouldin screws which were inserted in screws in close proximity to the considered appropriate.	dings were considered t milar products already o gs. This was retained by into pillars either side. T	o be of a lesser on the market. The PCB y the outer rims of The use of the metal



	Product Service
	BS 6004 electrical cable was fitted to the sockets conductors in addition to the connections already in place to the PCB. However it was difficult to retain both due to the differing gauges. It was noted the switch to one of the samples had been fitted incorrectly which prevented access to the screw. The PCB required removal to gain access to the conductor socket screw. Image: Constraint of the prevented access to the screw. Image: Constraint of prevented access to the screw. Image: Constrew. Image
	(BS 1363-2, Clause 9)
Constructional Quality	-Pass A-Fail
Comments	Only the live and neutral sides of the socket were shuttered. Further inspection revealed that these did not operate simultaneously as required by the standard. For the standard of the stan



	Terminals & Terminations	
Constructional	(BS 1363, Clause 11)	
Constructional Quality	Pass A-Fail	
Comments	A number of BS 1363 approved plugs failed to fully fit into the socket. It was found that the earthing pin required some manipulation to enable it to fully insert. This movement caused some deformation to live and neutral output conductors, potentially causing stress on to the attached input conductors.	
	Internal Wiring / Separation	
	(BS EN 61558-1, Clause 21)	
Constructional Quality	-Pass 🛛-Fail	
Comments	The output (SELV) circuit was found to be adequately separated from the input circuit. The PCB was fully exposed with no form of insulating material or encasement; therefore it is considered that live parts of the SELV circuit could come into direct contact with the protective earth if installed into a standard 35mm galvanised patress box. There was insufficient information on the wiring to enable verification of	
	any 3 rd party approvals.	
Screws, Current Carrying Parts & Connections (BS 1363-2, Clause 13)		
Constructional Quality	Pass -Fail	
Comments	The connections to the PCB were found to be mechanically secured and soldered.	

© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 4 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Cr	eepage Distances, Clearances & Distances Through Insulation		
	(BS EN 61558-1, Clause 26)		
Constructional Quality	Pass A-Fail		
Comments	The minimum creepage / clearance distance measured between the primary and secondary side of the circuit board (2.5mm) with a 1.3mm slot was found to be within the limit of the standard. There was a minimum distance measured between the primary and secondary transformer windings (3.7mm) therefore did not meet the requirement of the standard. A minimum of 5mm is required.		
	Short Circuit, Overload and Thermal Protection (BS EN 61558-1, Clause 15)		
Constructional Quality	Pass -Fail		
Comments	It is good practice to incorporate a fuse to the primary side of AC / DC circuit; however this was not present. Although not a requirement it is recommended that a thermal protective device is incorporated into the circuit.		
	Mechanical Strength		
Result	(BS 1363-2, Clause 20)		
Comments	A standard USB connector was placed in to the socket. This was subjected to an impact test of 5Nm to each side and around the facia / switch. No damage was observed to the USB port or socket face; however the switch assembly was forced inward on the first impact.		
	Insulation Resistance / Leakage Current		
Result	(BS EN 61558-1, Clause 18.2)		
Comments	The product was subjected to an insulation resistance test with a voltage of 500VDC applied. This was measured between live / neutral and the USB output. A measurement of >999M Ω was recorded across each path; therefore meeting the requirement of >5M Ω .		
	Electric Strength (BS 1262-2, Clause 15 / BS EN 61558-1, Clause 18)		
Result	(BS 1363-2, Clause 15 / BS EN 61558-1, Clause 18)		
Comments	The product was subjected to an electric strength test to 1500VAC. The output was tested to 4242VDC. No breakdown or flashover occurred.		



	Product Service
	Output Voltage & Current Under Load
Decult	(BS EN 62684, Clause 5)
Result	Pass A-Fail
Comments	The device was plugged in and the open circuit voltage measured across the USB ground and supply. It was found to be 5.229 VDC and was between the limits of 4.75 – 5.25VDC.
	There was no stated maximum output current for the USB socket. No short circuit test was possible as the sample had exploded before it could be completed.
	The device was setup with a load bank and the load slowly increased to 0.5A. The temperature was monitored around the device. After about 1.5 hours the sample exploded and the test was stopped. Both USB socket wires were blown off the PCB and it appeared an 8.2Ω surface mount resistor exploded.
	35.0 30.0 25.0 25.0 20.0 P 15.0 5.0 0.0 0.0 0.0 0.20:00 07:30:00 07:40:00 07:50:00 08:00:00
	Time T1=Left of USB socket T2=Right of USB socket T3=Base
	The maximum recorded temperature was 32.0°C.

© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 6 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Product Images

Internal Overview



Packaging

Internal Face



Markings



Internal Construction



Internal Construction



