

Safety Screening Report

Report:	071-75924520-302	Date:	09/01/2014
Client:	The Electrical Safety Council Unit 331 Great Guildford Business Square 30 Great Guildford Street London SE1 0HS		
Product:	Electrical Socket	ESC Sample Number:	1
Summary:	TÜV SÜD Product Service was commissioned by The Electrical Safety Council to evaluate an Electrical Socket (see figure 1). The aim of the assessment is to assess the product against the clients Safety Screening Test Plan.		

Summary

The product was of adequate external construction but it failed to accept several BS1363 plugs. Internal construction was poor and the product had several markings were also missing from the product.

Figure 1



Assessed by:

Anna Jeeves Consumer Product Technician

Reviewed by:



Greg Plummer Consumer Product Test Engineer





= Improvements Required



© 2014 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 1 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.





Testing Information				
Testing Laboratory:	TÜV SÜD Product Service			
Location:	Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire,			
	PO15 5RL. UK.			
Client:	The Electrical Safety Council			
ESC Sample Number:	1			
Product Information				
Product Description:	Single Wall socket with a USB Port			
Rated Input Voltage:	250VAC			
Rated Output:	5VDC / 500mA			
Protection Class:	Class I			

Findings					
Markings/Warnings					
(BS 1363-2, Clause 7)					
Marking of Product	🛛 🖂 - Inadequate 🔄 - Poor 🦳 -	Adequate 🔄 - Good 🔄 -	Very Good 🗌 -N/A		
Comments	The product was marked wit	h a model reference and	d electrical ratings. BS		
	1363 -2 was stated; however BS 1363 is only required. The distributor's				
	name / trademark, WEEE logo and CE marking were missing. These must be				
	added. The USB's electrical r	atings were noted to be	clearly visible to the		
	end user once installed. A small folded leaflet was provided with				
	instructions for installation which was considered to be suitable for a				
	qualified electrician. There w	as no operational or saf	ety advice provided for		
	the end user. The WEEE logo	and CE marking were a	iso missing from the		
Markings (Dhata		CE Marking			
iviarkings/Photo	If yes see last page of report	CE Warking			
	,,,.,.,.,.,.,.,.,.,.,.,.,.,.,.,.,,.,				
	External Cons	truction			
(BS 1363-2, Clause 13)					
Product Build Quality	Pass -Fail				
Comments	The external construction was of an adequate standard and considered				
	comparable to similar produ	cts already on the marke	et. No sharp edges,		
	burrs or pinch points were fo	ound. The product was s	upplied with self		
	tapping screws for attaching	the socket to a pattress	or back box. These		
	were not fit for purpose as th	ne socket became stuck	to the back box during		
	testing as the screws got jam	imed in the retaining me	etal nuts.		
Accessibility of Live Parts					
(BS 1363-2, Clause 9)					
Constructional	Pass -Fail				
Quality					
Comments	The product was assessed wi	ith the facia in situ and r	emoved. Access to		
	internal live parts could not b	pe achieved when apply	ing a 1.0mm calibrated		
	test pin to potential areas of	access, other than thos	e intended to be		
	exposed when installed or from	om inserting a plug.			



Terminals & Terminations					
Constructional	(BS 1363, Clause 11)				
Quality					
Comments	A number of BS 1363 approved plugs failed to fully fit into the socket. The				
	input conductors were noted to be adequately secured within the				
	mouldings. Appropriately sized / threaded screws were used.				
	Internal Wiring / Separation (BS EN 61558-1, Clause 21)				
Constructional	Pass -Fail				
Quality					
Comments	The output (SELV) circuit was separated from the input circuit and covered with boxed moulding which was adequately secured. The Live parts of the SELV circuit were not in direct contact with the protective earth. There was insufficient information on the wiring to enable verification of any 3 rd party approvals.				
	Connections				
	(BS 1363-2) Clause 13)				
	(b) 1909-2, clause 19,				
Constructional	Pass X-Fail				
Quality					
Comments	The connections to the PCB were found to be mechanically secured and soldered; however the connecting wires were tack soldered directly into the live / neutral conductors which prevented full insertion of the plug pins. It is recommended that connections of this type are mechanically secured in addition to soldering and situated as to not interfere with other connections.				
Creepage Distances, Clearances & Distances Through Insulation (BS EN 61558-1, Clause 26)					
Constructional	Pass X-Fail				
Quality					
Comments	The minimum creepage distance measured between the primary and				
	secondary side of the circuit board was found to be within the limit;				
	however a clearance distance of 2.25mm was measured. Although there				
	was the addition of a 1mm slot, it did still did not meet the minimum				
	requirement of the standard. There was no measurable distance between				
	the primary and secondary transformer windings (touching). The standard				
	requires a minimum of 5mm in both instances.				



Short Circuit, Overload and Thermal Protection (BS EN 61558-1, Clause 15)				
Constructional Quality	Pass -Fail			
Comments	A 1A, glass fuse was suitably fitted to the primary side of the circuit. There was no thermal protection present. Although not a requirement it is recommended that a thermal link is incorporated into the circuit.			
	Mechanical Strength			
	(BS 1363-2, Clause 20)			
Result	∐-PassFail			
Comments	Standard USB connectors were placed into each socket, These and areas			
	Some deformation of the socket's metal casing was noted: however this did			
	not affect the mechanical fit of a USB plug.			
	Insulation Resistance / Leakage Current			
	(BS EN 61558-1, Clause 18.2)			
Result	Pass -Fail			
Comments	The product was subjected to an insulation resistance test with a voltage of			
	500VDC applied. This was measured between live / neutral and the USB			
	output. A measurement of $>999M\Omega$ was recorded across each path;			
	Flectric Strength			
	(BS 1363-2, Clause 15 / BS EN 61558-1, Clause 18)			
Result	Pass -Fail			
Comments	The product was subjected to an electric strength test to 1500VAC. The			
	mains output was tested to 4242VDC. No breakdown or flashover occurred.			
	Output Voltage & Current Under Load			
(BS EN 62684, Clause 5)				
Result	The device was plugged in and the open signification measured across			
comments	the USB ground and supply. It was found to be 4.95 VDC and was between			
	the limits of $4.75 - 5.25$ VDC.			
	The stated output current was 500mA which is within the required limit of			
	1500mA.			
	Under short circuit conditions the product drow 0.011/0.165mA from the			
	USB port. The maximum sustainable load was just over 1.15A which is over			
	twice that stated.			
	The device was setup with a load bank and the load slowly increased until			







Product Images

Internal Overview



Rear

Internal Face



Fuse



