

Safety Screening Report

Report:	071-75924520-003	Date:	09/01/2014
Client:	The Electrical Safety Council Unit 331 Great Guildford Business Square 30 Great Guildford Street London SE1 0HS		
Product:	Electrical Accessory	ESC Sample Number:	3
Summary:	TÜV SÜD Product Service was commissione evaluate an Electrical Accessory (see figure	d by The Electrical 3 1). The aim of the a	Safety Council to assessment is to assess

the product against the clients Safety Screening Test Plan.

Summary

The product was of adequate construction although there is doubt about the authenticity of the plug and requires user instructions. The product failed to meet the requirements of BS EN 62684:2010 for output protection.

Figure 1



Assessed by:

0109

Anna Jeeves Consumer Product Technician

Reviewed by:

Greg Plummer Consumer Product Test Engineer



Amber

= Improvements Required



© 2014 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 1 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Testing Information	
Testing Laboratory:	TÜV SÜD Product Service
Location:	Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire,
	PO15 5RL. UK.
Client:	The Electrical Safety Council
ESC Sample Number:	3
Product Information	
Product Description:	Trailing socket with Integrated USB Port & Battery Charging Bays
Rated Input Voltage:	250VAC
Rated Output:	USB - 5VDC / 2100mA Max.
	Battery Charger – 1.4VDC / 160mA
Protection Class:	Class I

Findings			
Markings/Warnings			
(BS 5733, Clause 8)			
Marking of Product	Nadequate -Poor -	Adequate 🗌 - Good 🦳	-Very Good 🗌 -N/A
Comments	The product was adequately marked with all of the required information.		
	This included the model reference, input rating, output ratings (covering		
	each of the outputs), distributor trademark, CE marking and WEEE logo.		
	The relevant standards were stated; however BS 5733 should be marked as		
	BS 5733/A as it is a portable product.		
	The product was supplied in	an unmarked inlain whi	ite cardboard box with
	no instructional information	. It is expected that guid	lance regarding general
	safety, operation and compa	tibility would be provid	ed; however this was
	not supplied for the end user.		
Rating Plate/Photo	⊠-Yes □-No	CE Marking	🛛 -Yes 🗌 -No
	If yes see last page of report		
	External Cons	truction	
(BS 5733, Clause 13)			
Product Build Quality	Pass -Fail		
Comments	The external construction wa	as of an adequate stand	ard and considered
	comparable to similar produ	cts already on the mark	et. No sharp edges,
	burrs or pinch points were for	ound; however some de	formation of the
	sockets moulding was noted		
Accessibility of Live Parts			
(BS 5733, Clause 8)			
Constructional	Pass -Fail		
Quality			
Comments	The casings had been adequately secured with tamper-proof screws. Access		
	to internal live parts could n	ot be achieved when ap	plying a 1.0mm
	calibrated test pin to potent	ial areas of access.	



Terminals & Terminations	
	(BS 5733, Clause 14)
Constructional	└─J-Pass I⊠J-Fail
Quality	
Comments	The product was supplied with a Scolmore branded, class 1, BS1363 marked plug. The license number was verified online; however the quality of the materials used and lack of markings (part reference) were not considered to be of that usually seen by the brand. A check within a calibrated BS 1363 plug gauge revealed that the live pin was too short. Some lateral movement of the live pin was also observed. A check revealed that it was also difficult to insert / remove a number of BS 1363 approved plugs into the sockets. It was noted that the earth pin did not always fully engage before the live / neutral pins.
Internal Wiring / Separation (BS EN 61558-1, Clause 21)	
Constructional Quality	Pass -Fail
Comments	The output (SELV) circuit was found to be adequately separated from the input circuit. The Live parts of the SELV circuit were not in contact or exposed to earth.
	Screws, Current Carrying Parts & Connections
	(BS 5733, Clause 14 & 15)
Constructional Quality	Pass A-Fail
Comments	The connections to the circuit boards, switch and positive battery conductors where mechanically secured / soldered; however the connection to the negative battery conductor was soldered only. It is recommended that a secondary form of security is used. The quality of the manually soldered connections was considered poor. The neutral input connection to the switch was not secured. Some areas of corrosion to the battery conductors were also noted. The supply cords earthing conductor was found to be weaved through the switch's terminals which were not sleeved as expected. It was found that the sharp edges of the live connection had caused some damage to the sleeving.

Page 3 of 7



	The connections within the internal socket assembly were found to be
	either soldered or welded. It was found that that the quality of both methods of connection was inadequate
Creep	bage Distances, Clearances & Distances Through Insulation (BS EN 61558-1. Clause 26)
Constructional	⊠-Pass □-Fail
Quality	A minimum groopage (clearance distance of 4 9mm was measured
Comments	between the primary and secondary side of the circuit. The standard requires a minimum of 5.0mm; it was therefore considered to be on the limit. Better quality control would ensure this does not happen.
	The transformer was constructed with a triple-insulated secondary winding; therefore considered to provide an adequate barrier from the primary side.
	Short Circuit, Overload and Thermal Protection
Constructional	□ Pass □-Fail
Quality	
Comments	A fusible resistor was fitted to the primary side of the control circuit. Thermal protection devices were also found on the control circuit (x1) surge protection circuit (x2); however these did not carry any verifiable approvals markings.
	Mechanical Strength (BS 5733, Clause 21)
Result	Pass -Fail
Comments	The product was subjected to an impact test. This was carried out with the free end of the cable held against a wall with the cable held horizontally at 400mm above a hard floor then allowed to drop. This was repeated with the cord rotated through 45° at its fixing eight times. No damage was observed.

© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 4 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



	A standard USB connector was placed into the socket. This was then
	subjected to an impact test of 5nm to all sides. Some deformation of the
	sockets metal casing was noted; however this did not affect the mechanical
	fit of a USB plug.
	Insulation Resistance / Leakage Current (BS EN 61558-1, Clause 18,2)
Result	
Comments	The product was subjected to an insulation resistance test with a voltage of
	500VDC applied. This was measured between live / neutral and the USB
	output. A measurement of >999M Ω was recorded across each path;
	therefore meeting the requirement of >5M Ω .
	Electric Strength
Decult	(BS 5733, Clause 19 / BS EN 61558-1, Clause 18)
Result	The product was subjected to an electric strength test to 21211/DC. The
comments	mains output was tested to 4242VDC. No breakdown or flashover occurred
	Output Voltage & Current Under Load
	(BS EN 62684, Clause 5)
Result	Pass X-Fail
Comments	The device was plugged in and the open circuit voltage measured across
	the USB ground and supply. It was found to be 5.145 VDC and was between
	the limits of 4.75 – 5.25VDC.
	The stated output current was 2100mA which is above the required limit of
	1500mA. Under short circuit conditions a current of 4.1A was observed.
	This is above the required limit of 3A.
	The device was setup with a load bank and the load slowly increased until
	the voltage output dropped significantly. The load was then backed off until
	the voltage remained stable at a current of 2.6A and left to run. The
	After approximately 8 hours the device failed with no output.
	70.0
	Т
	e 50.0
	m 40.0
	30.0
	° 20.0 — T3
	CT4
	T5
	10: 11: 12: 12: 13: 15: 15: 15: 15: 15: 15: 12: 12: 12: 12: 12: 12: 12: 12: 12: 12
	Time

© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 5 of 7 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



T1=Left of USB socket
T2=Right of USB socket
T3=Base under USB socket
T4=Right of power switch
T5=Plug
The maximum recorded temperature was 64.3°C.



Product Images

Internal Overview (Main Assembly)





Internal overview (13A Sockets)



Control PCB



Plug



Fuse



